

case study

ACE DuraFlo Systems

Better than a Repipe...without Destroying Walls!

Pipe Restoration

Restoring Pinholed Copper Pipe in a Residence, Placentia, CA

The Problem:

Wet spots on the slab, wet spots on the ceiling are usually telltale signs of a leaking water pipe buried under a concrete slab or hidden behind a wall or ceiling. The homeowner of this 15 year old, 2 ½ bathroom residence was alarmed to find out that their copper piping system was failing due to the results of corrosion and poor plumbing. Pinhole leaks were emerging and the prognosis for repair at first suggested that a replacement of the entire piping system was inevitable.

Call the repiper? Maybe so but the best that could be offered by the repiper was to replace the entire piping system which meant plumbers, painters, tile setters and a cleanup crew would be spending at least a week in and out of the house, cutting into walls, ceilings and floors and then trying to match paint colors and work around existing décor. Finally cleaning up.

The Solution:

Call ACE DuraFlo! The ACE DuraFlo team of three uniformed technicians arrived at the residence and completed the project in less than a day and a half. After completing conventional repairs to the leaking sections of pipe, the system was restored. No walls, floors or ceilings were cut and the complete water supply system was restored using the ACE DuraFlo® system of in place pipe restoration. ACE DuraFlo restored this homeowners piping system using epoxy lining technology that relines the inside of the piping system with their approved epoxy lining. ACE DuraFlo epoxy lining materials are certified with NSF® and UPC®.



SOS Pipe Restoration
PO BOX 132
Westminster, CA 92684
800-400-4767