

case study

ACE DuraFlo Systems

Better than a Repipe...without Destroying Walls!




Pipe Restoration

IN SLAB PINHOLE LEAK – INSURANCE CLAIM

ACE DuraFlo® System Saves Money and Time and Proves to be a Huge Winner for Both Homeowner and Insurance Company.


The Problem – This Southern California homeowner had just experienced the mess, destruction and disruption to their lifestyle by having their home ripped apart to repair a pinhole leak located under the slab near the front entry of this upscale custom built home. For the insurance company this meant an expensive claim. The home originally had hardwood floors that had to be torn out to repair the leaky water line running under the slab. Tearing out the floor meant a new floor had to be replaced, repairs to all the main floor walls, installation of new baseboard and a complete repainting of the main level. The homeowner and family had to be temporarily relocated to a hotel, all at the expense of the insurance company. The job took several weeks to complete.



Not much more than a year later and to everyone's horror, less than 1 foot from the original leak, the homeowner noticed a new wet spot on the newly installed Travertine floor. A **NEW PINHOLE LEAK!**

The Solution – ACE DuraFlo® System of in place pipe restoration.

The insurance provider, AAA of Southern California contracted with ACE DuraFlo® who completed the repair and restoration of the piping system, in place. ACE DuraFlo® did not have to cut into the new Travertine flooring or the freshly painted walls. The homeowner's water piping is now protected by ACE DuraFlo's epoxy coating. The fear of another leak in the future is a thing of the past. The insurance carrier now has the option to continue coverage knowing that this type of claim will not occur again.



SOS Pipe Restoration
PO BOX 132
Westminster, CA 92684
800-400-4767

